

1.5/8"

N7340MXV1

**ADEMCO Model No. 5806
SMOKE DETECTOR/TRANSMITTER**

(FCC ID: CFS 8DL 5806A)

CANADA 1748 K1430

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE TWO FOLLOWING CONDITIONS: (1) IT MAY NOT CAUSE HARMFUL INTERFERENCE; (2) IT MUST ACCEPT ANY INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION.

NOMINAL SENSITIVITY 2.7 ± 1%/FT

USES TWO 9V ALKALINE BATTERIES (e.g. ADEMCO 464, EVEREADY 522 DURACELL MN 1604).

WARNING

- CONSTANT EXPOSURE TO HIGH OR LOW TEMPERATURES OR HIGH HUMIDITY MAY REDUCE BATTERY LIFE.
- BATTERIES MUST BE INSERTED WITH CORRECT POLARITY. TEST DETECTOR AFTER INSTALLATION FOR PROPER OPERATION.
- USE SPECIFIED BATTERIES ONLY; OTHER BATTERIES MAY CAUSE IMPROPER OPERATION.
- WHEN CHANGING BATTERIES, BOTH BATTERIES MUST BE REPLACED. WAIT 15 SEC. AFTER REMOVING OLD BATTERIES.

CONSTANT HORN INDICATES ALARM. REPLACE BOTH BATTERIES WHEN HORN BEEPS ABOUT ONCE PER MINUTE.

FOR INSTRUCTION AND OPERATION, REFER TO INSTRUCTION MANUAL.

DO NOT DISASSEMBLE FOR REPAIR. RETURN TO:
ALARM DEVICE MFG. CO. 149 EILEEN WAY
SYOSSET, NY 11791
A DIVISION OF PITTMAY CORP.


N219



LISTED

S1428

SINGLE STATION SMOKE ALARM

ISSUE NO: _____

TEST BUTTON 

3.00"

ADN7340MXV1
Rev.B 6/99